




Marathon Petroleum Company LLC

1300 South Fort Street
Detroit, MI 48217
Telephone 313/843-9100

FEDERAL EXPRESS

July 26, 2010

Director, Air Enforcement Division
C/O Matrix Environmental & Geotechnical Services
120 Eagle Rock Avenue-2nd Floor
East Hanover, NJ 07936



RE: Second Quarter 2010 Leak Detection and Repair, Wastewater VOC, and Benzene Waste NESHAP Certification and Compliance Report- Attachment A Fig.1 Schematic of Benzene Waste NESHAP Equipment.

The report submitted by the Michigan Refining Division of Marathon Petroleum Company LLC (MPC) dated July 21, 2010 and sent on July 23, the copy sent did not include Attachment A. Fig.1 "Schematic of Benzene Waste NESHAP Equipment".

Included and attached is the schematic of Benzene Waste NESHAP Equipment for the above mentioned Second Quarter Leak Detection and Repair, Wastewater VOC, and Benzene Waste NESHAP Certification and Compliance Report.

Please contact Ms. Kristen Schnipke (313) 297-4750 or Mr. Greg Shay (313) 297-6115 if you have any questions concerning this submittal.

Sincerely,


Greg Shay
Environmental Professional

Attachments

cc:

- (2) Air and Radiation Division, U.S. EPA Region 5 --*Federal Express*
- (2) Office of Regional Counsel, U.S. EPA Region 5 --*Federal Express*

Fig. 1 : SCHEMATIC OF BENZENE WASTE NESHAQ EQUIPMENT (02/16/07 - Present)



| LEGEND | |
|---|--------------------------------------|
| | TREATMENT PROCESS (61 348) |
| | ORGANIC WASTE (SUBPART FF) |
| | AQUEOUS WASTE (SUBPART FF) |
| | INDIVIDUAL DRAIN SYSTEM (controlled) |
| | EXEMPT FROM SUBPART FF |
| | CONTROL DEVICE/CLOSED-VENT SYSTEM |
| | SUBPART OQQ |
| | TEMPORARY FACILITIES |
| | SPENT CAUSTIC |

Revision Date: 7/14/2010
 *Yellow border indicates controlled devices.
 *Dashed lines are controlled.